


# TRANSPOWER<sup>®</sup> OIL FILTRATION & CONTRACTORS

## 1200 LPH Portable Filtration Plant

A Major cause of Transformer Failure is due to the presence of Moisture which destroys the insulating property of the oil & reduce the **DIE ELECTRIC STRENGTH** & the presence of particularize which reduce the heat Transformer Property and also result in wear of the contacts and coil due to abrasion and therefore, it is necessary to Filter the Transformer Oil as per IS:335 to reduce the moisture as well as acidity & increase the die electric strength to extend the **TRANSFORMER LIFE**.

**While cleaning systems suitable for online & offline filtrations.**



**OIL TEST KIT** :- The Oil Test Set is the microprocessor based test equipment that is designed to test the dielectric strength of insulating oil. The motorized oil test kit is of single phase and 240 volts. The tried and tested set yield a distortion free output. The optional magnetic stirrer facility is also available on request.

**Specification :-** **Input :** 220/230 AC-1 Phase 50Hz,  
**Output :** 0-60/75/100 KV centre tap earthed;  
**Capacity :** 1KVA; **Indication :** Mains ON and HT ON Lamps

- ✦ Transformer Repairing, Attending Heavy Leakages, maintenance of Transformer, Replacement of Bushing, Gaskets, Overhauling the Transformer, Repair of Change Over Switch and Cable Box.
- ✦ ACB, OCB, Panel Board & CTPT.
- ✦ Isolators, GOD, DOF, Maintenance, Spares Replacement, Greasing for smooth operation.
- ✦ Cable Lying, Cable Jointing.
- ✦ Street Light Pole Erection
- ✦ Earthing Testing & New Earthing Providing.
- ✦ **PAINTINGS**  
Transformer Painting, Panel Board Painting, 2 Pole & 4 Pole Structure Painting.



**“Taking Annual Maintenance Contract”**

# TRANSPOWER<sup>®</sup>

Head Office : 8/2, Shri Krishna Niwas, Ram Joshi Marg, Bhatwadi, Ghatkopar (W), Mumbai-84.

Tel.: 022-2512 5237 / 2510 7952 • Fax : 022-2502 2170 Mob.: 9820539902, 9920539902

E-mail : transp@mtnl.net.in • Web: www.transpowerindia.com